Facility ID#: 0-0/08% UST CLOSURE INSPECTION CHECKLIST _____Date_12-15-97 Inspector's Name I SITE INFORMATION Facility/Site Name: ITIAA- LONGVIEW COLF COURSE City/Town: 6321 BALLENGER ROAD 27410 County: GUILFORD Owner: Uramont TRIAD INTERNATIONAL AMPORT Phone: Operator: PTIAG - BIL SHAW ANTHORISONE: Contractor: AAD Phone: ANALYMIC Laboratory: PARADICM Phone: Directions: Date of scheduled UST Removal (from GW/UST-3): SANIA WERNER-EZS, LTD. II UST STATUS Tank #: 1 Size: 1000 Product: GASOUNE Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each of the following: III <u>CLOSURE PROCEDURES</u> Tanks, tools, equipment bonded or grounded? OSHA/Safety violations observed: Product in piping drained into tank? Tanks properly purged? Method: DRy DCS Tanks emptied and cleaned properly? Accessible openings capped or plugged except 1/8" vent? UST(s) closed in place and filled with solid inert material? Final destination of tank(s): A Final destination of product, contaminated soil, contaminated water, etc. A+D ENVIRONMENTAL GETS TANK ATA PUMPED TANK, WILL PUT GAS BACK INTO ABOVE GROUND TANK IV SITE DESCRIPTION Soil stained and/or petroleum odor? Contaminated soil excavated? Quantity? (estimate): Soil samples taken of excavated soil left on site? Excavated soil on plastic or trucked away? (Circle one) \// Tank(s) condition: No HOLES NOTES Product line condition?: V SAMPLING LOCATION USTs < 20': one at each end? USTs > 20': one at each end & middle? Samples every 20' of piping? Samples under each tank island? Water samples? (in lieu of soil samples) Samples: floor, side, stockpiled soil?:

Facility	ID#:
VI SAMPLE COLLECTION QUALITY CONTROL	
Collection method: (Shovel, auger, back hoe): How Preserved? (ice) Tools decontaminated: (soap, Di-H ₂ O, MEOH, organic-fr Chain-of-Custody form (required):	ee H ₂ O).
VII SUMMARY OF SITE CONDITIONS	
Groundwater intersected? H Contaminated soil? N Free product in excavation?	
VIII SAMPLES COLLECTED BY DEM PERSONNEL	
Samples collected? Sample locations: 2 UNDER TANK, I UNDER PRODUCT LINE, I UND XV COMMENTS: MITZI RUE TIME MITTALL	on P.I.
JERRU RICE-AND SHAWN TUCKER.	,
DIAGRAM OF SITE INVESTIGATION AT UST CLOS	URE
Diagram should include physical structures such as roads, former location of USTs, pumps, product lines; soil sample location of excavated soil.	buildings, etc.;
INDOCHH CART SHE	>
Cos Hoose	·